

Southern WV Accident Alert







Mine Safety and Health Administration

Preventive Practices:

- After idle periods the lead bridge operator must receive confirmation from all bridge operators that the system is ready for activation.
- Before leaving the operator's compartment each operator must ensure that the system is disabled.
- A position occupied switch should be used to disable the entire system, when an operator leaves the U.S. Department of Labor cab.